



A (x1)      B (x1)


|                                                                                                           |                                                                                                         |                                                                                                           |
|-----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| <br>M-A (x4)<br>M6x14    | <br>M-B (x4)<br>M8x20  | <br>M-C (x4)<br>Ø15xØ8x5 |
| <br>W-A (x2)<br>ST6.3x55 | <br>W-B (x2)<br>Ø10x45 | <br>W-C (x2)<br>D6       |




1




2




3




✓    ✗    ✗




Ø4.5mm (Ø3/16")  
55mm (2.2")



Ø10mm (Ø3/8")  
60mm (2.4")





W-C    W-A




W-B    W-C    W-A

4




✗    ✓


5



6



7



**Note:** If the display does not stop at your desired position, adjust the two side screws alternately using the tools as shown.