




A (x1)



B (x1)



C (x1)



D (x1)




E (x1)



F (x1)



G (x1)



H (x1)



I (x1)
M5x16



J (x1)
M10x20



K (x3)
M6x10



L (x1)
4mm



M (x1)
6mm



M-A (x4)
M4x12




M-B (x4)
M5x12




M-C (x4)
D5


1



2 Clamp Mounting




Grommet Mounting



Desktop with Existing Through-Hole.
ø10-60mm

10-40mm


OR



10-40mm


ø 10mm
(ø 3/8")

OR




10-40mm

45-85mm



3




4





Too long Too Short



M-A
M-B
M-C

TOP

5

